

# Rope Life Increased and Threading Improved By Correcting Rope Grooves

“Copley Rope Savers” are installed quickly and easily during a scheduled shutdown or wash-up. Shutdowns relating to rope problems can be very costly. By simply making adjustments to the rope grooves and sheaves can often eliminate those costly unscheduled shutdowns. Fluoron, Inc. proudly offers the Copley Rope Saver - a heat-shrinkable band, custom manufactured for each problematic rope groove or sheave. The result is smooth and durable with better-than-new finish. The Copley Rope Saver can correct problems such as rough or contaminated grooves or sheaves, variation in groove depths, oddly sized dryer grooves, and more. Installation is quick and easy and can be completed during a regularly scheduled shutdown. With Copley Rope Savers on your machine, you can avoid costly premature rope failure!

*“Our rope threading specialists will agree that the most common cause for premature rope wear comes from worn dryer grooves and sheaves. The best way to eliminate rope related down time is with proper upkeep of the rope run and scheduled rope changes coupled with proper rope sizing.” John Feola - General Manager - Cristini S.p.A.*  
Fluoron, Inc., [www.fluoron.com](http://www.fluoron.com)



**Short rope life remedied by resurfacing rope grooves.**